The attachment contains information affecting the National Defense of the Unite States within the meaning of the espionage laws, Title 18, U.S.C., Secs. 793 and 794, the transmission or revelation of which in any manner to an unauthorized person is prohibited by law.

| | i | / | Vo Days L, Sor 6 |
|--|---|---|--|
| | FOR INTERNAL | ROUTING ONLY | |
| CODE | NAME | CODE | NAME |
| | APOLL | 0 - 1 | DSE |
| | 1 | 1 1 | |
| · · · · · · · · · · · · · · · · · · · | Unboas | d Voi | ce Trans- |
| a | criptio | | Page in SII 2/26 brief "my best flyst". 29 SECO 36 |
| Hey lost the | Bum compette: 84 | A. C. | SECO 36 |
| mon 73 | Bonnani "So to bed" 162 | | TEI chuhlist 241-47 |
| and the second | Borner: "So to bed" 162 Pleners 195 Borner: Served made me sick." | 1233 | "We've going home," |
| 1 mm mm m | "Hey, I gos the moon" | 13 | Bonden 248 |
| 100 | First AOS "Calm Drum, Lovelle" | 88 | "Int tol a grant of 2 |
| The second secon | lost contact or exact presiden | | Borner : T've fort wot , 237 "Come on John Glenn" 260 |
| 2 | Von Braun, America 103, | | |
| | Tswellowsky Can | 149 | |
| 306 | "Shire me the camera, quick | 152 2 113 | |
| | Gente shot) 198 | T. | |
| | The come on the come" | | |
| 20 20 20 20 20 20 20 20 20 20 20 20 20 2 | Bornes: "hops to be like ine on be going the other | in to 229 | |
| | Anders "Yhat did you | | 0.6 |

ALL CONFIDENTIAL MATERIAL IN THE POSSESSION OF NASA MUST HAVE THIS FORM
ATTACHED WHEN NOT IN STORAGE

CONFIDENTIAL

UNCLASSIFIED WHEN DETACHED FROM CLASSIFIED MATERIAL

| | | | CONFIDENTIAL Day 4 224 |
|----------|---------------------|-----|--|
| Ç | 03 16 32 58 | CDR | Do you? |
| <u>.</u> | 0 3 16 33 00 | LMP | Yes. |
| | 0 3 16 33 01 | CMP | You do? |
| | 03 16 33 02 | CDR | I feel like I've been in the whole time like I've been here in the simulator. |
| | 03 16 33 04 | CMP | Yes, that's right; me too. |
| • | 03 16 33 05 | CDR | I've been lying on my |
| | 0 3 16 33 06 | CMP | The only difference is that this is |
| | 0 3 16 33 07 | LMP | I feel like I'm in the DCPS. |
| | 03 16 33 08 | CDR | Oh, really? |
| | 03 16 33 09 | LMP | Yes. |
| | 03 16 33 13 | CMP | 0key |
| | 03 16 33 14 | IMP | little bit. |
| | 03 16 33 24 | LMP | I'm giving these an extra little whack here just so there won't be any surprises. |
| | 03 16 33 35 | CMP | (Singing) |
| | 03 16 33 52 | CMP | 42 is a pretty small star, too: Peacock. |
| | 03 16 34 19 | CMP | Why don't you let the old DAP take it from here? |
| | 03 16 34 21 | CDR | I'm going to. As soon as we get in close, I'm going to give it to the DAP. It's going faster than the DAP can take roll it's going the way we want it to go. |
| | 03 16 34 30 | CMP | You going to align the GDC here? (Yawn) |
| | 03 16 34 35 | CDR | Yes. I left it this way so we can tell where we're pointing |
| | 03 16 34 39 | CMP | On. |
| | | | |

Where's the earth; can you see it?

I left her in ORB RATE.

03 16 34 40 CDR

03 16 34 51 LMP

| 3. | 03 16 34 53 | CDR | No. Oh, it's out here, Bill - up this way. |
|----------|---------------------|-----|---|
| . | 03 16 34 57 | LMP | Okay. Getting the right antenna. |
| | 03 16 35 01 | CMP | Okay, so what we are going to do is pitch down this way, huh' |
| | 0 3 16 35 37 | LMP | We've got an earthset picture for Life megazine! |
| | 03 16 35 40 | CDR | We're there! |
| | 03 16 35 42 | LMP | Okay, are you there? |
| | 03 16 35 44 | CDR | Yes. |
| | 03 16 35 46 | LMP | Okay, you want AUTO trim? |
| | 03 16 35 50 | CDR | Yes, a little AUTO trim. |
| | 03 16 35 54 | IMP | Okay, CMC and AUTO. |
| | 03 16 35 55 | CDR | Right. |
| | 03 16 35 56 | LMP | Proceed. |
| | 03 16 35 57 | CDR | Right. |
| ķ., | 03 16 35 58 | IMP | Boresight and sextant star check. |
| | 03 15 36 00 | CDR | Okay. |
| | 0 3 16 36 01 | IMP | You're kind of in deep trouble for doing that. It's impossible. |
| | 03 16 36 05 | CDR | You're looking right at the moon. |
| | 03 16 36 06 | LMP | Yes, you have to wait awhile. |
| | 03 16 36 09 | CDR | Gee, that's a pretty interesting view, isn't it? That earthshine is bright. |
| | 03 16 36 12 | CMP | Let me take a look. |
| | 03 16 36 14 | LMP | When the earth sets, then we'll have enough |
| | 03 16 36 15 | CDR | Look down here. |
| | 03 16 36 17 | CMP | Huh! |

| 0 3 16 36 20 | DR See it? | |
|-------------------------------|--------------------------------------|---|
| 03 16 36 21 0 | ① Oh, yes, I see | it quite well. |
| 03 16 36 26 L | P Oh, I might be What was the - | able to ε t a star up there, though. what was my star? |
| 03 16 36 30 C | P Your star was S | corpia Delti - Delta. |
| 03 16 36 34 L | P And which way w | as it? |
| 03 16 36 38 C | P Okay, it was do | wn 06.9 - |
| 03 16 36 44 L | P Yes. | |
| 03 16 36 46 C | P And left 4.5. | |
| 03 16 36 48 C | Oh, you'll neve | r get that. |
| 03 16 36 49 14 | P Well, how in th | e hell would you ever get it? |
| 0 3 1 6 36 50 C | R Well, there are | some stars up here, see, that just |
| 03 16 36 51 11 | P Yes. | |
| 03 16 36 53 C 1 | Yes. But Scorp | o is |
| 03 16 36 54 LA | You're not going near just prior | to be able to get it until damn to ignition. |
| 03 16 37 00 C I | R That's an inert: | al star. |
| 03 16 37 02 LA | Yes, but you've | got an inertial moon in your way. |
| 03 16 37 04 CN | Well, if it - it and it doesn't h | the COAS - if you set the COAS alt the moon, then it's okay. |
| 03 16 37 10 LM | ? That's right. 1 (laughter), look | t's kind of hard not to hit it though ing down at it like this. |
| 03 16 37 19 CM | I think you're 1 | ooking at Saturn. |
| 03 16 37 20 II | Well, I can't ev | en see I'm not getting in your way, am I? |
| 03 16 37 26 LM | CLaughter) You | guys - really bad! |
| 03 16 37 31 CD | | ng to put this thing INERTIAL - INERTIAL ting, OFF; select one - IMU. |

| 1 | '03 16 37 50 CMP | I could - I guess I could get out the optics and set the thing all the way up. All I'd have to do is wait until we get there. |
|---|---|--|
| | 03 16 38 03 CMP | You guys could go shead with the checklist without me in case I don't pick it up right away. |
| | 03 1 6 38 09 LMP | Look at that red star going down there. |
| | 03 16 38 10 CDR | I was trying to figure out what that was, too, Bill. |
| | 03 16 38 12 CMP | It might be Antares. |
| | 03 16 38 16 IMP | Boy, they set in a hurry, don't they? |
| | 03 16 38 21 CDR | They sure do. |
| | 03 16 38 24 LMP | Well, it's Scorpia, maybe it was - Yes? |
| | 03 16 38 30 CMP | That wouldn't be setting now, would it? |
| | 03 16 38 32 CDR | Yes, it would be. If it's going to be part of the boresight star, it's got to be near the horizon - near the plus-X axis |
| | 03 16 38 46 CDR | Okay, Bill, that should complete it. |
| | 03 16 38 48 LAP | Okay. |
| | 03 16 38 54 CDR | I won't be able to get a boresight star because we'll be in the daylight. |
| | 03 16 38 59 LMP | What about Jim? |
| | 0 3 1 6 3 9 0 0 C DR | Well, I don't know; I hope he can. |
| | 03 16 39 04 CDR | Are you going to do that before we press on, Jim? |
| | 03 16 39 07 LMP | When we get - when we get |
| | .03 16 39 10 CMP | Why don't I just set |
| | 03 16 39 11 IMP | your double umbra, why, you can do it then. |
| | 03 16 39 13 CMP | What's this double umbra? |
| • | 03 16 39 15 LMP | Double shadow. When the earth sets, then you will be able to - you'll be looking at 90 degrees back and you can look right down on it. |

| 3 , | 03 16 39 25 | CMP | When the earth sets? |
|-------------|-----------------------------|----------|---|
| (4) | 0 3 16 3 9 26 | LMP | Yes, the umbra is the shadow. |
| | 0 3 16 39 27 | CMP | Oh, yes, okay. |
| - | 03 16 39 30 | LMP | So we're in the shadow of the sun; that's the umbra of the moon, and when we're in the shadow of the earth, that's the umbra. You should be able to get a boresight star pretty soon, because we're going to come to the end of the - |
| | 03 16 39 41 | CMP | Are we? Okay, I'll go down there and set it |
| | 03 16 39 43 | LMP | Wait a minute. Where in the hell are we? |
| | 03 16 39 45 | CDR | Confusing. |
| | 03 16 39 48 | CMP | We're pitching down this way. |
| | 03 16 39 51 | LMP | We aren't doing snything - are we? Are we maneuvering? |
| | 0 3 16 39 54 | CMP | No, we're not. We're holding steady, but |
| | 03 16 39 55 | CDR | Here, let me show you |
| | 03,16 39 56 | LMP | Yes, that's right; we're not 90 degrees from our burn - from our burn place yet. If we're 90 degrees from our burn place, we'll be looking straight at the moon |
| | 0 3 16 40 03 | CMP | We're over here. |
| | 0 3 16 40 07 | LMP | We're coming this way. |
| | 03 16 40 08 | CMP : | Yes, I know. And we're not upside down like that. We're - Well - You have - Your optics are up. |
| | 0 3 16 40 18 | IMP | Optics are posigrade. They'll go to up. |
| | 03 16 40 28 | CDR | We're going right through here. |
| | 03 16 40 58 | CMP | Okay, Bill, when do you start reading the 6-minute checklist? |
| | 03 16 41 03 | LMP | 6 minutes. |
| | 03 16 41 04 | CMP | What's that time in GET? |

| 03 16 41 07 | LMP | Well, let's see here. 89:19 we'll call it; let's make it 89:13, okay? And the 5 one will be at 89:14, and the 2 will be at 89:17 - 35 - |
|---------------------|-------|---|
| 03 16 42 08 | CMP | I'm just looking where the PITCH 2 and YAW 2 circuit breakers are. I want to make sure you pull the right one. |
| 03 16 42 14 | CDR | YAW 2 and PITCH 2. |
| 0 3 16 42 16 | CMP | Okay. |
| 03 16 42 26 | CDR | I'm really screwed up. It looks to me we ought to be going the other way. |
| 03 16 42 30 | CMP | Yes, I know. |
| 03 16 42 31 | CDR | Huh? Yes, well, look. Well, here we are right here. |
| 03 16 42 34 | CMP | Oh boy! |
| 03 16 42 35 | CDR | What's wrong? |
| 03 16 42 36 | CMP | I should have got down here a long time ago. |
| 0 3 16 42 39 | CDR | Here's where we're going to be when we burn, right? |
| 03 16 42 40 | IMP | Yes, and we're right here now. See? And we're looking straight down at the moon, and the earth is over here. |
| 03 16 42 54 | CDR | Are you doing your star check? |
| 0 3 16 42 56 | CHE | Yes, right in a crater! |
| 0 3 16 42 59 | LMP . | Okey, you're not going to be able to do it until we get past this |
| 05 16 43 04 | CMP | Now, if I can't do it until real late, go - Start without me. |
| 03 16 43 10 | IMP | You'll be able to do it - You're 15 minutes - 20 minutes out of the burn. |
| 03 16 43 42 | CMP (| I wonder if the moon is made out of basically the same material as the earth is. |
| 03 16 43 46 | CDR | I don't know. |
| 03 16 43 48 | LMP | Probably is. |
| | | |

```
03 16 43 52 CDR
                        Anders is going to tell you when he alights from
                        the first LM - Pick up all the gold.
 03 16 44 07 CMP
                        I think he doesn't have to; he knows it all right now.
                        Didn't you hear him? Ye geologists of the world: I see a few grabens, a few slipped discs.
 03 16 44 39 LMP
                        There's a strange light down there.
 03 16 44 45 CDR
                        Is it a bonfire?
 03 16 44 47 LMP
                        It might be campfires.
 03 16 45 03 CMP
                        How does it look?
 03 16 45 07 LMP
                        I think you're going to be able to see it pretty soon.
                        Well, I'll put it in and wait for it.
 03 16 45 14 CMP
 03 16 45 16 CDR
                        Okay.
 03 16 45 20 CMP
                       Do I have the computer?
 03 16 45 22 CDR
                       Yes, ENTER the -
 03 16 45 30 CMP
                       Are you going to read this off to me?
 03 16 45 32 CDR
                       Yes, what is it?
 03 16 45 34 CDR
                       Bill?
 03 16 45 35 LMP
                       Okay, I'm getting the timer.
 03 16 45 42 LMP
                       Oh boy, we're going to get that damned thing to 10 again.
 03 16 45 50 LMP
                       Okay. Have that time -
03 16 46 01 LMP
                       You got a star, Jim?
03 16 46 02 CDR
                       No, he needs it read off to him.
03 16 46 04 LMP
                       Okay, OPTIC MODE, CMC.
03 16 46 07 CMP
                       Okay.
03 16 46 08 IMP
                       In zero OFF.
03 16 46 09 CMP
                       Zero OFF.
                         CONFIDENTIAL
```

| <- €: | 03 16 46 10 | LAP | VERB 41, NOUN 91, ENTER. Okey, we're going to lose them here pretty soon. |
|----------|---------------------|-----|---|
| | 03 16 46 23 | CMP | Okay. The shaft is 09240, plus |
| | 03 16 46 33 | LMP | You want me to write - to log this? |
| | 03 16 46 34 | CMP | 09240. Okay. ENTER. And the trunnion is plus 25300. Plus 25300. ENTER. |
| | 03 16 47 14 | LMP | There's no trouble reading by sorthophine. |
| | 03 16 47 19 | CMP | Oh, I don't have anything yet. |
| | 03 16 47 21 | CDR | Have you got the earth - the moon, I mean? |
| | 03 16 47 25 | CMP | I can't see either. |
| | 03 16 47 35 | CMP | I think I'm still on the earth - or the moon. |
| | 03 16 47 41 | LMP | What is your - what's your shaft and trunnion? Jim? |
| | 03 16 47 48 | CMP | Shaft is 02940. |
| | 03 16 47 51 | LMP | 02940, yes. |
| | 03 16 47 52 | CMP | Left 25.3 degrees trunnion. |
| | 03 16 47 55 | LMP | Oh, well, you're looking down at its eye. You've got to wait until you get down past the 90-degree point. |
| | 0 3 16 48 04 | CMP | I think I see it coming up. |
| | 03 16 48 09 | CC | Apollo 8, Apollo 8, Houston; 3 minutes LOS; all systems are GO. Over. |
| | 03 16 48 14 | CDR | Roger. Thank you, Houston; Apollo 8. |
| | 03 16 48 40 | CMP | I see the limb, and I see the stars coming up. |
| | 03 16 49 02 | LMP | Have you got optics power, zero - Oh, you haven't done that yet, huh? |
| | 0 3 16 49 06 | CMP | No, I'm waiting until I - until I see the star. |
| | 0 3 16 49 08 | LMP | Yes. |
| | 03 16 49 26 | CAP | How much time do we have? CONFIDENTIAL |

٠.

| : | 03 16 49 30 | CDR | Half an hour. |
|---|---------------------|-------------|---|
| i | 03 16 49 49 | CMP | There's our friend out there. |
| ÷ | 03 16 49 51 | IMP | You can really see Australia or something down there on the earth I get earthset here in just a second. |
| | 0 3 16 50 08 | C DR | Any luck, Jim? |
| | 0 3 16 50 11 | CMP | It's coming up, but I think I can almost verify it right now because I have Gruis, and Peacock is in line with the bottom parts of Gruis, and this optics |
| | 0 3 16 50 18 | CDR | We're not in any hurry. |
| | 0 3 16 50 19 | CMP | is exactly in line with it. I know, I was just saying that we can almost verify it right now. |
| | 0 3 16 50 56 | LMP | This is a pretty |
| | 0 3 16 50 57 | c c | All systems are GO, Apollo 8. |
| | 03 16 50 58 | LMP | Look at that, look at that, Frank. |
| | 03 16 50 59 | CDR | Thank you. |
| | 03 16 51 00 | LMP | Look at the earth. |
| | 03 16 51 03 | CDR | Yes. |
| | 0 3 16 51 04 | CMP | Setting? |
| | 03 16 51 05 | CDR | Yes. |
| | 03 16 51 08 | LMP | Yes, we're down in Carnarvon. |
| | 03 16 51 10 | CMP | Huh? |
| | 03 16 51 11 | LMP | Yes, we're down in Honeysuckle; that was Australia. |
| | 0 3 16 51 20 | LMP | You don't see that very often, do you? |
| | 03 16 51 47 | CDR | Okey? |
| | 0 3 16 51 50 | CMP . | No, the moon's still there. I see it coming up. Stars are coming up, but the moon is still there. Now, if you guys want to go on a little further, go ahead without me. |

| ∢. €.% | 03 16 51 59 | CDR | Oh, we got a lot of time. |
|-----------|---------------------|-------------|--|
| | 0 3 16 52 05 | CMP | I should see Peacock rise over that - I'm just amazed the way this thing operates. |
| | 03 16 52 24 | CDR | It's be n a pretty fantastic week, hasn't it? |
| | 0 3 16 52 29 | CMP | It's going to get better. |
| | 03 16 52 31 | CDR | Yes. |
| | 03 16 53 09 | CMP | This is utterly fantastic, though. This pawl line is lined up exactly with Gruis. |
| | 0 3 16 53 27 | CDR | You know what I think made me sick that night? |
| | 03 16 53 29 | IMP | What? |
| | 03 16 53 30 | CDR | That damned pill I took. |
| | 03 16 53 32 | LMP | What pill did you take? |
| | 03 16 53 34 | CDR | Seconal - one of the big ones. |
| | 03 16 53 36 | IMP | Oh, is that right? |
| | 03 16 53 37 | C DR | I didn't know you had small ones. I'd have taken one of those. |
| | 03 16 53 42 | IMP | Maybe you just had the flu. |
| | 03 16 53 44 | CDR - | Maybe I did, I don't know, but it seems like you guys would have gotten it. |
| | 0 3 16 53 50 | CMP | Well, I think that basically your stomach was just upset - because you can get it very easily - There's nothing wrong, you know. |
| | 0 3 16 53 54 | CDR | Yes, I know, but I never had it before, not even in zero-g airplane, which is a - a real - |
| | 03 16 54 39 | LMP | I hope this baby holds out for another 2-1/2 days. It sure has performed admirably, hasn't it? |
| | 03 16 54 44 | CDR | Yes. |
| | 03 16 54 52 | CMP | Gentlemen, Peacock should be rising above the moon right now. |
| _ | - | | CONFIDENTIAL |

| Z | 03 16 55 12 | CMP | And there it is. Just a minute, and I'll verify it. |
|---|---------------------|-------------|---|
| _ | 03 16 55 33 | C | Okay, I confirm Peacock. |
| | 03 16 55 35 | C DR | Okay, Bill, checklist. |
| | 03 16 55 36 | LMP | Okey. |
| | 03 16 55 41 | CDR | You can leave that off - Looks like we're going to be burning in the daylight anyway. |
| | 03 16 55 47 | LMP | Okay. Drive trunnion if less than 5 degrees. |
| | 03 16 55 51 | C!:P | Okay. Optics, zero, zero. |
| i | 03 16 55 53 | LMP | And GEN POWER OPTICS, OFF. |
| | 03 16 55 55 | CMP | Optics, zero. Don't hit the IMU switch; OPTICS, OFF. |
| | 0 3 16 56 02 | IMP | Okay, why don't you - Frank, you can have your lights up, I guess - Unless you wanted to check your star. |
| | 03 16 56 09 | C∴P | Too late, I'm not checking |
| | 0 3 16 56 10 | Lip | Frank, let me come down the other side. |
| | 03 16 56 12 | CDR | I doubt if I'll be able to. |
| | 0 3 16 56 13 | LP | No, I mean around the other side. |
| | 03 16 56 17 | IMP | I guess you probably won't; you'll be pitched into the moon, won't you? |
| | 0 3 16 56 18 | CDR | Yes, that's the trouble, I - I just barely get - and then when I do see it, I see a lit horizon. |
| | 03 16 56 27 | LMP | Okay, VERB 37, ENTER; 40, ENTER. |
| | 0 3 16 56 35 | LMP | BMAG MODE, three, RATE 2. |
| | 03 16 56 36 | CMP | Just a minute. |
| | 03 16 56 43 | CDR | BMAG, RATE 2. |
| | 03 16 56 45 | IMP | SPACECRAFT CONTROL, CMC. |
| | 03 16 56 49 | CDR | CMC. |

```
CMC MODE, AUTO.
 03 16 56 50 IMP
 03 16 5€ 51 CDR
                       .OTUA
 03 16 56 52 LMP
                       Proceed.
 03 16 56 54 CDR
                       Okay.
 03 16 56 59 IMF
                       Okay, align spacecraft roll to GDC. You got -
03 16 57 09 CDR
                       Okay.
03 16 57 10 LMP
                       16 minutes. Do you want to wait awhile to do this?
03 16 57 13 CDR
                       Well, it's already aligned. I'll do it now, Bill -
                       I don't think I'll have to do much - Put in a little
                       bit of yaw that way.
03 16 57 29 IMP
                       Okay, align spacecraft roll and GDC aligned. We'll
                       trim it again here - before the burn.
03 16 57 36 LMP
                       STABILITY CONTROL SYSTEM's circuit breakers, panel 8, CLOSED.
03 16 57.40 CDR
                       Alright. Now, let's watch this, Jim.
03 16 57 43 IMP
                      Direct ullage -
03 16 57 44 CDR
                      Don't want to leave that out.
03 16 57 45 LMP
                      I'm going to check mine over here, toc.
03 16 57 51 CDR
                      They're all CLOSED.
03 16 57 52 LMP
                      Okay, SPS circuit breakers CLOSED except for gaging.
03 16 57 57 CDR
                      Gaging OPEN, okay; PITCH 1, YAW - 2, PITCH - YAW 1, YAW 2. They're in.
03 16 58 06 CMP
                      They're in - okay.
03 16 58 10 CDR
                      Okay.
03 16 58 11 LMP
                      I'm just chees
                                      all mine here.
03 16 58 15 CDR
                      Don't push on them when you've got ...
                      I'll get them.
03 16 58 20 LMP
```

```
03 16 58 26 LMP
                      Okay, DEADBAND, MIN.
03 16 58 29 CDR
                      DEADBAND going to MINIMUM - MINIMUM!
03 16 58 31 LMP
                      RAFE, LOW.
03 16 58 32 CDR
                      LOW.
03 16 58 33 IMP
                      LIMIT CYCLE, ON.
03 16 58 34 CDR
                      ON.
03 16 58 36 LAP
                      MANUAL ATTITUDE, three, RATE COMMAND.
03 16 58 37 CDR
                      RATE COMMAND.
03 16 58 39 IMP
                      BMAG MODE, three; ATT 1/RATE 2.
03 16 58 42 CDR
                      ATT 1/RATE 2.
03 16 58 44 IMP
                      ROTATIONAL CONTROL POWER DIRECT, both, OFF.
03 16 58 47 CDR
                      DIRECT. Okay, that's OFF.
03 16 58 50 LMP
                      SCS TVC, two, RATE COMMAND.
03 16 58 53 CDR
                      SCS TVC, two, RATE COMMAND.
03 16 58 56 LMP
                      TVC GIMBAL DRIVE: PITCH and YAW, AUTO.
03 16 58 59 CDR
                      AUTO.
03 16 59 00 LAP
                      And here's where we stop -
03 16 59 01 CDR
                      Alright.
03 16 59 02 LMP
                     For 13 minutes.
03 16 59 27 LMP
                     Boy, it's blacker than pitch out here.
03 16 59 29 CDR
                      Yes, I know it.
03 16 59 37 CMP
                     Okay, (yawn) you're going to burn with the lights on
                     anyway, aren't you, because you've got to get sunlight.
03 16 59 40 CDR
                     Probably will, yes.
```

| ₹ & | 03 16 59 44 | CMP | Yes, I watched the sun - I watched that star rise, and I could just see the black horizon - the moon fade away and the star come up and - right on it. |
|-------------------|---------------------|-----|---|
| | 03 17 00 11 | IMP | Okay, if we get a MAIN A or an AC 1 failure, you change gimbal drives, right? |
| | 0 3 17 00 16 | CDR | Okay. |
| | 03 17 00 19 | LMP | You get a MAIN B or an AC 2 failure, don't change gimbal drives or do anything, except put your gimbals to from AUTO to 1. |
| | 03 17 00 36 | CMP | (Singing) |
| | 03 17 01 24 | IMP | Do you see anything hanging around that could come down? |
| | 03 17 01 28 | CDR | I hope not. |
| | 03 17 01 53 | CDR | Tell you one thing these flights are good for: an old fatty like me, I but I've lost a lot of weight. I didn't eat much those first two days, and I didn't - didn't even get much to eat today. |
| | 03 17 02 23 | CDR | When is the ignition, 89:19, huh? |
| | 03 17 02 27 | LMP | Yes. |
| | 03 17 02 29 | LMP | Pretty sunrise. |
| | 03 17 02 32 | CDR | Yes. |
| | 03 17 02 47 | CMP | I'm doing a P23 right after we leave this place, huh? |
| | 03 17 02 51 | CDR | Yes. |
| | 03 17 03 04 | CDR | Is it boiling, Bill? |
| | 03 17 03 06 | LMP | No, I hope not. It looks low. It's just cold in there. |
| | 03 17 03 21 | CMP | It does look a little low. When did I say I had the star? |
| | 0 3 17 03 28 | CDR | What time? |
| | 03 17 03 29 | LMP | Huh? |
| | 03 17 03 30 | CMP | Because we still have 60 degrees to go then, if we want to be parallel - perpendicular - horizontal to the horizon. CONFIDENTIAL |

```
03 17 03 39 LMP
                      Perpendicular (laughter)! ...
                      The horizontal, because I was 60 degrees down and I -
03 17 03 40 CMP
                      I just saw the - -
                      We're still looking at the moon - flat at the moon.
03 17 03 47 LMP
03 17 03 53 CMP
                      Well, not really.
03 17 03 54 LMP
                      Not flat at it.
03 17 03 55 CMP
                      I hope not.
                      Oh, no, not flat at it, but - Boy, it's black out there.
03 17 03 56 CDR
                      If you don't get G&N ignition, what are you going to do?
03 17 04 33 LMP
03 17 04 36 CDR
                      Go right to SPS.
03 17 04 38 LMP
                      Wouldn't it be smart to take it around again?
03 17 04 40 CDR
                      Why? If we didn't get it this time, why would we get
                      it better the next time?
03 17 04 47 LMP
                      The burn ... - -
03 17 04 48 CDR
                      There's a 10-degree excursion on this thing.
03 17 04 53 LMP
                     Make sure you hit the corridor.
03 17 05 14 CDR
                     You're right. It would be smart to take it around again.
03 17 05 18 LMP
                     Get set up to do an SPS burn, huh?
03 17 05 20 CDR
                     AUTO SPS.
                     I haven't looked at your G - you might still be able
03 17 05 23 LMP
                     to get - -
                     Wait a second; let me check it.
03 17 05 27 CDR
                     - - to get G&N errors.
03 17 05 28 IMP
                      (Singing, whistling)
03 17 05 38 CMP
                     Now, you should see something - Yes, there it comes.
03 17 06 17 IMP
                     Where do you see it?
03 17 06 20 CDR
                       CONFIDENTIAL
```

| Ţ | 03 17 06 21 | CMP | 6 minutes to recheck. |
|---|-------------|---------------|--|
| • | 03 17 06 22 | CDR | Oh, yes, it |
| | 03 17 06 24 | LL/IP | I see it off the side of the terminator from sunrise. |
| | 03 17 06 34 | CMP | I wonder if that - that sort of a zodiacal light was a glare off the optics, cr something. |
| | 03 17 06 40 | ИP | You ought to draw a little picture of it, and people could tell you what it was. |
| | 03 17 06 49 | CDR | You got the gimbal thing handy right off the bat? |
| | 03 17 06 53 | IMP | Yes, why don't we write that down? |
| | 03 17 06 54 | C DR | Minus 0 |
| | 03 17 06 55 | CMB\IWB | 40 plus 157. |
| | 03 17 07 00 | CDR | Is it 157? Not 151? |
| | 03 17 07 06 | CMP | I'll check on the 11 pad. 157. |
| | 03 17 07 10 | CDR | Okay. |
| | 03 17 07 11 | CMP | in there. |
| | 03 17 07 13 | LMP | I bet we had the - The weight hadn't - the trim hadn't changed any since the last time. (Laughter) Getting worried there for a minute. |
| | 03 17 07 21 | CMP | We've been eating a lot of food. |
| | 03 17 07 24 | CDR | Let's see now, that's 2 - 2 minutes and 13 seconds, is that what we said? 2:18. |
| | 03 17 07 31 | CDR | 138 seconds. |
| | 03 17 07 34 | CI- IP | 2:18 must give you a slow return home. |
| | 03 17 07 35 | CDR | Yes, |
| | 03 17 07 37 | LMP | You got your strut in? |
| | 03 17 07 41 | CDR · | Yes, it's in. |

| 03 17 07 44 | IMP | Probably, one of the things we've been hearing is these oxygen masks snapping up and down. |
|--------------------|---------|--|
| 03 17 08 02 | IMP | Boy, it took three acts of Congress to get those little strings. |
| 03 17 08 07 | LMP | Oh, that - that's peculiar, isn't it? |
| 03 17 08 12 | CDR | Yes, looks to me like we're going right at it. Doesn't it look like that to you? |
| 03 17 08 19 | CMP | Why is it we do all these burns upside down? |
| 03 17 08 21 | CDR | So you can see. |
| 03,17 08 23 | CMP | (Laughter) You want to look at that? |
| 03 17 08 25 | CMP/CDR | (Laughter) |
| 03 17 08 28 | LMP | If it makes you feel bad, look out the side windows. |
| 03 17 08 31 | CDR | Yes, I think it would look better. |
| 03 17 08 39 | CDR | I've got - coming up on 10 minutes. |
| 03 17 10 12 | CDR | Okay, 9 minutes, right now on - |
| 03 17 10 17 | CDR | MARK. |
| 03 17 10 27 | CMP | (Singing) |
| 03 17 10 42 | LMP | Hey, don't forget your ullage. |
| 03 17 10 43 | CDR | Yes, gees, don't let me forget that! |
| 03 17 10 45 | LMP | How many seconds do you need? |
| 03 17 10 47 | CDR | 15 seconds. |
| 03 17 10 48 | CMP . | Four-jet ullage. |
| 03 17 10 49 | IMP | Okay, we better write that down. |
| 03 17 10 55 | LMP | Ullage will be at 89:19:01. Okay? |
| 03 17 11 02 | CDR | Yes. You're going to call it off, right? |
| 03 17 11 07 | IMP | Weil, I'll try to remember - Got it in here. |
| | | |

Day 4

241

| 03 17 11 11 | CDR | Oh, yes. |
|---------------------|-------------|---|
| 03 17 11 14 | CMP | Yes, "ullage as required" down there, I got. You'll see the 15 seconds right on here. |
| 03 17 11 20 | LMP | 15 seconds. |
| 03 17 11 23 | C DR | Yes. |
| 03 17 11 24 | CMP | |
| 03 17 11 59 | CMP | All it does is let you see whether it is there or not; then if it is, it doesn't do anything. |
| 03 17 12 03 | IMP | Yes, I know, but it drifts off a little. The deadband affects it, I guess. |
| 03 17 12 07 | CMP | Oh |
| 0 3 17 12 16 | LMP | Boy, you think you're going to burn right into the water - I mean, right into the sand. |
| 03 17 12 18 | CMP | Did you have trouble scooping up those type of rocks? You said you went up to West Texas for that. |
| 03 17 12 24 | CDR | 7 minutes, coming up on 6 minutes. |
| 03 17 12 27 | LMP | Okey. |
| 0 3 17 12 28 | CDR | Let's go ahead and start. |
| 03 17 12 39 | IMP | Okay, MAIN BUS ties are coming ON. |
| 03 17 12 40 | CDR | Okay. |
| 03 17 12 44 | LMP | A is ON; B is ON. |
| 03 17 12 51 | IMP | Okey. SPS, TVC, two, RATE COMMAND; and TVC GIMBAL DRIVE, PITCH and YAW in AUTO. Recheck them. |
| 03 17 13 01 | CDR | RATE COMMAND and AUTO. |
| 03 17 13 02 | IMP | Okay, TVC SERVO POWER 1, AC 1, MAIN A. |
| 03 17 13 05 | CDR | AC 1, MAIN A. |
| 03 17 13 06 | LMP | 2, AC 2, MAIN B. |

| 03 17 13 09 | CDR | Right. |
|----------------------------|-------------|--|
| 03 17 13 10 | LMP | TRANSLATIONAL CONTROL POWER, ON. |
| 03 17 13 12 | CDR | TRANSLATIONAL CONTROL POWER, ON. |
| 03 17 13 14 | LMP | ROTATIONAL CONTROL POWER NORMAL 2, AC. |
| 03 17 13 17 | CDR | AC. |
| 03 17 13 18 | IMP | ROTATIONAL HAND CONTROLLER number 2, ARREED. |
| 03 17 13 22 | CDR | ARMED. |
| 0 3 17 13 28 | IMP | Stand by to start the GIMBAL MOTORS. |
| 03 17 13 30 | C DR | Okay. |
| 03 17 13 34 | CDR | Should I pull the circuit breakers? |
| 03 17 13 35 | LMP | No, not yet! |
| 03 17 13 37 | CDR | Okay, just checking. |
| 03 17 13 46 | IMP | Okey, let's start PITCH 1 and YAW 1. |
| 03 17 13 48 | CDR | Alright, ready; PITCH 1. |
| 03 17 13 50 | IMP | Got it. |
| 03 17 13 51 | CDR | YAW 1. |
| 03 17 13 52 | LMP | Got it. |
| 03 17 13 53 | CDR | Okey. |
| 03 17 13 54 | IMP | Okay, clockwise. |
| 03 17 13 55 | CDR | Clockwise. |
| 03 17 13 56 | IMP | Verify no MTVC. |
| 03 17 13 57 | CDR | No MTVC. |
| 03 17 14 00 | IMP | Okay. Start PITCH 2 and YAW 2. |
| 03 17 14 03 | CDR | PITCH 2. |

```
Got it.
03 17 14 04 IMP
03 17 14 06 CDR
                     YAW 2.
03 17 14 07 LMP
                     Got it.
03 17 14 09 CDR
                     Okay.
                     Set GPI trim.
03 17 14 10 IMP
                     Okay, minus 40, plus 157.
03 17 14 11 CMP
03 17 14 16 LMP
                     Got it.
                     Verify MTVC.
03 17 14 18 LMP
03 17 14 20 CDR
                     MTVC.
                     TRANSLATIONAL HAND CONTROLLER, NEUTRAL.
03 17 14 21 LMP
03 17 14 23 CDR
                     NEUTRAL.
                     GPI returns to zero.
03 17 14 25 LMP
03 17 14 27 CDR
                     Zero.
                     ROT CONTROL POWER NORMAL 2, AC/DC.
03 17 14 28 LMP
                     AC/DC.
03 17 14 31 CDR
03 17 14 32 IMP
                     Want to trim? Yes.
03 17 14 34 CDR
                     Yes.
                     Okay. BMAG MODE, three, RATE 2.
03 17 14 35 LMP
                     RATE 2.
03 17 14 37 CDR
03 17 14 38 LMP
                     S - SPACECRAFT CONTROL, CMC and AUTO.
03 17 14 40 CDR
                     Right.
03 17 14 41 LMP
                     Proceed.
03 17 14 42 CMP
                     Proceed.
```

Okay.

03 17 14 45 CDR

Day 4

244

```
Okay, EMAG MODE, three, ATT 1/RATE 2.
03 17 14 47 LMP
                      ATT 1/RATE 2.
03 17 14 50 CDR
                      ENTER.
03 17 14 51 UMP
03 17 14 52 CMP
                      ENTER.
                      Okay. Gimbal test option, ACCEPT; SPACECRAFT CONTROL,
03 17 14 54 LMP
                      CMC; verify.
03 17 15 00 CDR
                      Proceed, huh?
                      Proceed.
03 17 15 01 LMP
03 17 15 02 CDR
                      Right.
                      Proceed.
03 17 15 03 CMP
03 17 15 04 LMP
                      Call them out.
                      Alright. 20, minus 20, 00, 02, 0 minus 2, 00.
03 17 15 05 CDR
03 17 15 20 CMP
                      Whew!
03 17 15 21 LMP
                      60 40; check your clock.
                      60 40; clock is good.
03 17 15 24 CDR
                      ROT CONTROL POWER DIRECT, both, MAIN A, MAIN B.
03 17 15 26 LAP
                      MAIN A, MAIN B.
03 17 15 29 CDR
                      SPS HELIUM VALVES, both, AUTO.
03 17 15 30 LMP
03 17 15 32 CDR
                      Verified.
03 17 15 34 LMP
                      LIMIT CYCLE, OFF.
03 17 15 36 CDR
                      LIMIT CYCLE, OFF.
03 17 15 37 LMP
                      FDAI scale, 50/15.
                      50/15.
03 17 15 39 CDR
                      Pull PITCH 2 and YAW 2.
03 17 15 40 LMP
                      Alright, watch this.
.03 17 15 42 CDR
```

```
PITCH 2; YAW 2.
03 17 15 43 CDR
03 17 15 47 LMP
                      Stand by for 2 minutes.
03 17 15 50 CDR
                      Okay.
03 17 15 51 IMP
                      How's your boresight star?
03 17 15 54 CDR
                      Hey, listen. It looks to me like I'm going to burn right
                      into the ground. Oh! There's the horizon. Hurray!
                      We're going the right way.
03 17 16 02 UP
                      Boy, you sure can't tell when you're - -
03 17 16 03 CMP
                      3.2 degrees at T<sub>ig</sub> minus 3.
03 17 16 07 CDR
                      What is it?
03 17 16 08 CMP
                      3.2 degrees at T minus 3 - right about now.
03 17 16 11 CDR
                      Okay, I can - It looks good.
                      We've got to arm this TRANSLATIONAL HAND CONTROLLER.
03 17 16 18 CDR
                      Did you tell me to do that?
03 17 16 24 CDR
                      Then, we've got to ullage.
03 17 16 25 LMP
03 17 16 40 CDR
                      Okay, coming up on 2-1/2 rinutes.
                      Okay, 5 seconds after you start, get DELTA-V THRUST B,
03 17 16 47 LMP
                      ON, okay?
03 17 16 52 CDR
                      Okay, yes. Then I'm all set.
03 17 16 56 LMP
                      Don't forget to start your watch, Jim. Reset it now.
03 17 16 59 CMP
                      Yes, it's all reset.
                      Okay, DELTA-V THRUST A, NORMAL.
03 17 17 03 LMP
03 17 17 06 CDR
                      NORMAL.
03 17 17 07 LMP
                      TRANSLATIONAL HAND CONTROLLER, ARMED.
03 17 17 09 CDR
                      ARMED.
```

```
ROTATIONAL HAND CONTROLLER, both, ARMED.
03 17 17 10 LMP
03 17 17 12 CDR
                      ARMED.
                      TAPE RECORDER - -
03 17 17 14 LMP
03 17 17 24 CDR
                      Okay.
                      How's it look?
03 17 17 39 LMP
03 17 17 40 CDR
                      Good.
03 17 17 43 LMP
                      I'm going forward (laughter).
03 17 17 46 LMP
                      Well, ... - -
                      ... a hell of a kick in the pants now, I'll tell you that.
03 17 17 48 CDR
03 17 17 54 CDR
                      The DSKY blanks at 35 seconds, right?
                      Right, it comes back on at 30; 15 seconds later you
03 17 17 56 LMP
                      give it the ullage.
                      What'll I have?
03 17 18 05 CDR
                      TRANSLATION CONTROL.
03 17 18 07 LMP
                      You got one DELTA-V THRUST, ON?
03 17 18 16 LMP
03 17 18 17 CDR
                      One ON, one ON.
03 17 18 18 LMP
                      Okay.
03 17 18 19 LMP
                      A, ON.
03 17 18 20 CDR
                      A is ON.
03 17 18 25 LMP
                      Don't forget the -
03 17 18 27 CDR
                      5 seconds.
03 17 18 28 LMP
                      2 to 5 seconds.
03 17 18 29 CMP
                      Right.
                      Okay, she blanked.
03 17 18 41 CDR
                      She blanked.
03 17 18 42 CMP
```

```
03 17 18 43 CDR
                     Okay.
03 17 18 45 LMP
                      EMS MODE, AUTO.
                      AUTO.
03 17 18 46 CDR
                     FLIGHT RECORDER going to RECORD,
03 17 18 47 LMP
03 17 18 48 CMP
                      Stand by to start ullage.
03 17 18 50 LMP
                     Proceed.
03 17 18 51 CMP
                     Proceed.
                     I'll give you a mark for ullage.
03 17 18 55 LMP
03 17 18 56 CDR
                     Okay.
03 17 18 58 CMP
                     He's got it right here.
                     17, 16 -
03 17 19 00 LMP
03 17 19 02 CMP
                     MARK.
03 17 19 03 LMP
                     Ullage!
03 17 19 06
            LMP
                     Proceed when you need to.
03 17 19 12 CMP
                     Proceed.
03 17 19 13 CDR
                     I'm proceeding.
03 17 19 16 LMP
                     Two valves. Good shape - -
03 17 19 21 CDR
                     Two valves.
03 17 19 22 LMP
                     Four valves.
                     Pressure's holding.
03 17 19 32 CMP
03 17 19 43 LMP
                     It's looking real good.
03 17 19 45 CDR
                     Pressure ...
03 17 20 16 LMP
                     Burned for 1 minute.
                     Okay.
03 17 20 18 CDR
```

| | 03 17 20 51 | LMP | It's looking good. |
|---|---------------------|-----|--|
| • | 03 17 20 52 | CDR | Lock should |
| | 03 17 21 12 | LMP | Coming up on 2 minutes. |
| | 03 17 21 16 | LMP | 2 minutes. |
| | 03 17 21 28 | IMP | 132 seconds. |
| | 03 17 21 36 | CDR | We're going home. / 3 5 |
| | 03 17 21 37 | CMP | Keep her going. |
| | 03 17 21 44 | CDR | Boy, those g's are building up as it gets lighter. |
| | 03 17 21 55 | CMP | Okay, we're coming down the pike. |
| | 03 17 22 01 | CDR | We've got to trim this one, too. |
| | 0 2 17 22 03 | CDR | 30 seconds. |
| | 03 17 22 27 | LMP | Stand by. |
| | 03 17 22 35 | LMP | 5, 4, 3, 2, 1 - |
| | 03 17 22 40 | LMP | STOP. |
| | 03 17 22 41 | CDR | Okay. |
| | 03 17 22 42 | LMP | Well, that wasn't much of a cutoff there (laughter). |
| | 03 17 22 44 | CMP | It sure wasn't. |
| | 03 17 22 45 | CDR | Okay, let's go. |
| | 03 17 22 47 | LMP | Okay. Four valves, CLOSED; helium, CLOSED; DELTA-V THRUST A and B |
| | 03 17 22 50 | CMP | 26.4. |
| | 03 17 22 51 | LMP | OFF. |
| | 03 17 22 54 | CDR | DELTA-V THRUST A and B are OFF. |
| | 03 17 22 57 | IMP | Okay, put the PITCH 2 and YAW 2 circuit breakers IN. Turn them OFF slowly. |